Millivolt Pilot Valve Kit Trouble Shooting

IT IS EXTREMELY RARE FOR A THERMOCOUPLE OR VALVE TO FAIL DUE TO DEFECT. SEE BELOW <u>BEFORE</u> REMOVING EITHER FROM THE FIREPLACE.

<u>Symptoms</u>	Possible Cause	Solution
Pilot won't light.	 Gas line not bled to let gas reach pilot. Pilot adjustment screw not open far enough. Gas not reaching pilot because valve is installed backwards. Pilot gas supply tube burned or crimped. Knob on valve not being pushed in far enough. Pipe dope or tape used on thermopile connections. Soot or rust covering outlet hole on pilot orifice. 	 Bleed lines. Open pilot adjustment screw. (Turn to Left). Re-install Valve. Replace pilot burner assembly. Route away from main burner flame. Push in about 1/4". Remove pipe dope or tape. Clean thoroughly and open hole with Soft brush.
or no	mopile lead too tight ot tight enough at valve. ation burned off thermopile	 Make sure pilot flame is strong and is hitting thermopile. 1a) Make sure thermopile is paint, carbon & rust free. 1b) Hold knob on valve in longer. Adjust to finger tight + 1/4 turn. Replace and route away from main burner flame.
Pilot lights but burner won't.	 Gas not getting to burner. Valve control not set to ON position Valve/Receiver not wired correctly. Pilot Burner Assembly to valve n wired correctly Gas not getting to burner due to debris in line. 	2) Rewire.
Pilot lights, burner lights, but system goes out after a while.	1) Thermopile over heating.	1) Consult Instructions
Flames come out of holes on air/mixer orifice (LP systems)	 Air mixer/orifice installed incorrectly. Possible back pressure from elbow installed after air/mixer going to burner pan Possible paint over spray in the burner ports. 	 Install air mixer/orifice so long end and air holes face toward valve (away from main burner). Reinstall air mixer so it is going straight into burner pan Check all ports in burner pan and ream out all that may be clogged
Whistling Sound	 Seldom caused by pilot. Possibly a too small flex 	 Check log set burner, orifice (if used) and amount of material covering burner. Use minimum ½" OD connector.
Soot on Logs	connector. 1) Rarely caused by pilot.	Check for flame impingement on logs. Adjust air mixer if using LP.